



Success Story

October 7, 2004

On extended sea trials this past weekend (10 hours running), my Yanmar engines never exceeded 185 degrees F. This is a major improvement over the high temperatures I have been experiencing for sometime and I might say after \$2,300 plus dollars of mechanic bills to try and get the temperature down to normal. I was facing thousands more to take the heat exchangers etc off the engines and have them cleaned. For less than \$250 (pump, hoses, clamps and **RYDLYME Marine** product), I cleaned the entire system – heat exchanger, lube oil cooler, transmission cooler, air cooler and all internal raw water passages. Your product more than exceeded what I was hoping for. I am a happy camper to have such a nagging problem solved.

Sincerely,

O.T. Atkinson, Jr.
Ft Myers, Florida